

SHIP SURVEY STATUS

TAG 13

Registered Owner : TAG OFFSHORE LTD.



IR Number : 43961

IMO Number : 9680827

Ship Type : AHT/OSV

Gross Tonnage : 2267

Date of Build : 15/01/2014

Survey Status Generated on : 09/07/2019



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Table of Contents

Ship Particulars

Owner / Manager Information

Class / Statutory, ISM, ISPS, MLC Certificates

Survey / Audit / Inspection Status

Condition of Class

Statutory Condition

Memoranda

Additional Information

Compliance to New Regulations

Continuous Survey List(s)

List of Surveyable Items

Survey History - 5 Year Survey Cycle

Information for ship owners / managers

IRCLASS Contacts



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Ship Particulars

Identification

| | | | |
|------------------------|---|-------------------------|------------------------------------|
| <i>Ship Type</i> | : AHT/OSV | <i>Flag</i> | : INDIAN (Merchant Shipping Act) |
| <i>Official No</i> | : 4137 | <i>Port of Registry</i> | : Mumbai |
| <i>Call Sign</i> | : AWFH | <i>Date of Registry</i> | : 17/10/2013 |
| <i>For Indian Flag</i> | : Registered under: - Merchant Shipping Act | <i>Ex. Name / Flag</i> | : Excelsior |

Classification

Class Notation Hull : ANCHOR HANDLING TUG, SUL, "OFFSHORE SUPPORT VESSEL"

Class Notation Machinery : IY, AGNI 1 (2400M3/HR), DP(2)

| <i>Class History</i> | <i>Ship Status</i> | <i>From Date</i> | <i>To Date</i> | <i>Reason</i> | <i>Remarks</i> |
|----------------------|--------------------|------------------|----------------|----------------|----------------|
| | Classed | 16/01/2014 | 15/01/2019 | - | |
| | Suspended | 15/01/2019 | | Survey Overdue | |

Hull

| | | | |
|---------------------------------|-------------|-------------------------------|-----------------------------|
| <i>Gross Tonnage</i> | : 2267 | <i>Builder</i> | : Fujian Southeast Shipyard |
| <i>Net Tonnage</i> | : 680 | <i>Place of Built</i> | : FUZHOU, CHINA |
| <i>Deadweight</i> | : 1964.42 T | <i>Yard No.</i> | : DN65M-1 |
| <i>Light Ship</i> | : 2040.86 T | <i>Date of Build</i> | : 15/01/2014 |
| <i>Anniversary Date</i> | : 14-JAN | <i>Keel Date</i> | : 06/05/2013 |
| <i>Overall Length</i> | : 65 m | <i>Building Contract Date</i> | : 20/02/2012 |
| <i>LBP</i> | : 58.5 m | <i>Major Conversion Date</i> | : |
| <i>Breadth</i> | : 16 m | <i>Depth</i> | : 6.2 m |
| <i>Draught</i> | : 5.2 m | <i>Equipment Ltr</i> | : T |
| <i>Ballast Wtr Capacity(m³)</i> | : 726.06 m³ | <i>Chain Quality Type</i> | : CC3 and Chain Dia. 38 mm |
| | | <i>Freeboard</i> | : 1010 mm |

Machinery

| | | | |
|--------------------------|--|--------------------------------|---|
| <i>Main Engine Model</i> | : 8MG28HX | <i>Electrical Installation</i> | : 3 Diesel Generators of Cater Pillar Inc, Power : 450 KW each 415V, 50Hz; Model : C18 |
| <i>Total power</i> | : 4854 kW | | 1 Diesel Generators of Cummins, Power : 99 KW each 415V, 50Hz; Model : 6CTA8.3-D(M) |
| <i>Stroke</i> | : 370 mm | <i>Bore</i> | : 280 mm |
| <i>Engine Builder</i> | : Niigata Power System Co. Ltd. Yokohama (Japan) | | 2 Diesel Generators of Niigata Power Systems Co. Ltd., Power : 1000 KW each 415V, 50Hz; Model : 8MG28HX |
| <i>Engine built</i> | : 24/04/2013 | <i>Boilers</i> | : |
| <i>Propeller</i> | : Controlled pitch propeller | | |
| <i>Speed</i> | : 14.2 Knots | <i>RPM</i> | : 184 |
| <i>Bollard Pull</i> | : 84.2 T | | |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Owner /Manager Information

Registered Owner

Name : TAG OFFSHORE LTD.
Address : Unit No. 201, A Wing , 2nd Floor, Neelam Center
Hind Cycle Marg
Next To Omkar 1973,Worli
Mumbai ,
India
Pin Code:400 030
Phone:67887852
Email:Tagoffshore.Cirb@Gmail.Com

Invoicing Address

Name : TAG OFFSHORE LIMITED
Address : C/O Regus, Room No. 102 , 1st Floor, Block A
Dr. Annie Besant Road
Level 1, Shiv Sagar Estate
Worli-Mumbai , Maharashtra
India
Pin Code:400018
Email:Tagoffshore.Cirp@Gmail.Com

Manager ISM / ISPS / MLC

Name : TAG OFFSHORE LIMITED.
Address : Unit No. 201, A Wing, 2nd Floor
Neelam Centre
Hind Cycle Marg
Next To Omkar 1973
Worli, Mumbai - 400 030
India.
Company ID : 5097701



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Class / Statutory, ISM, ISPS, MLC Certificates

The Class / Statutory, ISM, ISPS, MLC Status below shows the information available in IRCLASS database at the time the status is printed. This may not indicate certificates issued, surveys carried out or recommendations issued but not yet reported to Head Office.

Note : Cert. Issued Mode - HC = Hard Copy, DC = Digitally Signed Copy

Cert. Type - FT = Full Term, ST = Short Term, ET= Extended Term , INT = Interim , PROV = Provisional

[Kindly click here to navigate the detail informations related to electronic certificates.](#)

| Certificate name | Issued Date | Issued By | Expiry Date | Cert. Type | Cert. Issued Mode |
|--|-------------|-----------|-------------|------------|-------------------|
| Class Certificate | 26/04/2017 | IRS | 14/01/2019 | FT | HC |
| Statutory Certificate | | | | | |
| <i>Cargo Ship Safety Construction Certificate</i> | 17/05/2017 | IRS | 14/01/2019 | FT | HC |
| <i>Cargo Ship Safety Equipment Certificate (SEQ)</i> | 11/04/2015 | IRS | 14/01/2019 | FT | HC |
| <i>Cargo Ship Safety Radio Certificate (SRT)</i> | 17/05/2017 | IRS | 14/01/2019 | FT | HC |
| <i>Cert. of Fitness for OSV (LHNS-OSV)</i> | 11/04/2015 | IRS | 14/01/2019 | FT | HC |
| <i>Compliance To AFS Certificate</i> | 11/04/2016 | IRS | | FT | HC |
| <i>IMDG Code Compliance Certificate</i> | 11/04/2015 | IRS | 14/01/2019 | FT | HC |
| <i>International Air Pollution Prevention Certificate</i> | 11/04/2015 | IRS | 14/01/2019 | FT | HC |
| <i>International Energy Efficiency Certificate</i> | 11/04/2015 | IRS | | FT | HC |
| <i>International Loadline Certificate</i> | 11/03/2014 | IRS | 14/01/2019 | FT | HC |
| <i>International Oil Pollution Prevention (IOPP) Cert.</i> | 11/04/2015 | IRS | 14/01/2019 | FT | HC |
| <i>International Sewage Pollution Prevention Cert.</i> | 20/06/2017 | IRS | 14/01/2019 | FT | HC |
| <i>Special Purpose Ship (SPS) Safety Certificate</i> | 06/04/2018 | IRS | 14/01/2019 | FT | HC |
| Statutory Audits / Inspections | | | | | |
| <i>ISPS Code Certificate</i> | 01/08/2014 | GOI | 16/06/2019 | FT | |
| <i>MLC Inspection Certificate</i> | 27/07/2017 | IRS | 26/07/2022 | FT | HC |
| <i>Safety Management Certificate</i> | 09/01/2018 | GOI | 16/06/2019 | FT | |
| <i>Document of Compliance (DOC - ISM) Cert. (Other Cargo Ship)</i> | 04/12/2017 | GOI | 14/09/2019 | FT | |



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Surveys / Audits / Inspections Status

Classification Surveys

| Survey Name | Assigned Date | Due Date | Range Date | Status |
|--|---------------|------------|--------------------------|---------|
| Special Survey Hull | 15/01/2014 | 14/01/2019 | 14/01/2019 | Overdue |
| Intermediate Survey | | | | |
| <i>Intermediate Survey (Complete) 01/04/2017</i> | | | | |
| Annual Survey | 13/03/2018 | 14/01/2019 | 14/10/2018 To 14/01/2019 | Overdue |
| Docking Survey | 12/01/2017 | | | |
| <i>Previously done on 15/01/2014</i> | | | | |
| Renewal Docking Survey | | 14/01/2019 | 14/01/2019 | Overdue |
| Special Survey Machinery | 15/01/2014 | 14/01/2019 | 14/01/2019 | Overdue |
| External Fire Fighting (AS) | 13/03/2018 | 14/01/2019 | 14/10/2018 To 14/01/2019 | Overdue |
| Dynamic Positioning System - Annual Survey | 13/03/2018 | 14/01/2019 | 14/10/2018 To 14/01/2019 | Overdue |
| External Fire Fighting(SS) | 15/01/2014 | 14/01/2019 | 14/01/2019 | Overdue |
| Dynamic Positioning System - Special Survey | 15/01/2014 | 14/01/2019 | 14/01/2019 | Overdue |
| Tailshaft (oil gland), Port | 15/01/2014 | 14/01/2019 | 14/01/2019 | Overdue |
| Tailshaft (oil gland), Starboard | 15/01/2014 | 14/01/2019 | 14/01/2019 | Overdue |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Statutory Surveys

| Statutory Certificates Status | Last Survey Date | Survey Carried Out By | Range Dates | Status |
|---|------------------|-----------------------|-------------------------|---------|
| Cargo Ship Safety Construction Certificate | 13/03/2018 | IRS | 14/10/2018 - 14/01/2019 | Overdue |
| Cargo Ship Safety Equipment Certificate (SEQ) | 13/03/2018 | IRS | 14/10/2018 - 14/01/2019 | Overdue |
| Cargo Ship Safety Radio Certificate (SRT) | 13/03/2018 | IRS | 14/10/2018 - 14/01/2019 | Overdue |
| Cert. of Fitness for OSV (LHNS-OSV) | 13/03/2018 | IRS | 14/10/2018 - 14/01/2019 | Overdue |
| Compliance To AFS Certificate | 12/03/2015 | IRS | | |
| IMDG Code Compliance Certificate | 12/03/2015 | IRS | | Overdue |
| International Air Pollution Prevention Certificate | 13/03/2018 | IRS | 14/10/2018 - 14/01/2019 | Overdue |
| International Loadline Certificate | 13/03/2018 | IRS | 14/10/2018 - 14/01/2019 | Overdue |
| International Oil Pollution Prevention (IOPP) Cert. | 13/03/2018 | IRS | 14/10/2018 - 14/01/2019 | Overdue |
| International Sewage Pollution Prevention Cert. | 30/03/2016 | IRS | | Overdue |
| Special Purpose Ship (SPS) Safety Certificate Special Purpose Ship (SPS) Safety Certificate Annual | 13/03/2018 | IRS | 14/10/2018 - 14/01/2019 | Overdue |

Statutory Audits / Inspections

| Statutory Certificates Status | Last Audit Date | Audit Carried Out By | Range Dates | Status |
|---|-----------------|----------------------|-------------------------|---------|
| ISPS Code Certificate (Coastal) (Full Term) ISPS Code Certificate Renewal Audit <i>ISP Intermediate : completed on 24-APR-17</i> | 24/04/2017 | GOI | 16/03/2019 - 16/06/2019 | Overdue |
| MLC Inspection Certificate (Full Term) MLC Inspection Certificate Intermediate | 27/07/2017 | IRS | 26/07/2019 - 26/07/2020 | |
| Safety Management Certificate (Full Term) Safety Management Certificate(SMC) Renewal Audit <i>SMC Intermediate : completed on 17-MAY-17</i> | 17/05/2017 | GOI | 16/03/2019 - 16/06/2019 | Overdue |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Condition of Class

*** No COC Recommended ***

Statutory Condition

*** No Statutory Condition Recommended ***

Memoranda

*** No Memoranda Recommended ***

Additional Information

| Code | Previous Reference | Prev Ref Dt | Mod | Current Reference | Curr Ref Dt | Asgn |
|---|-----------------------|-------------------|-------------|-----------------------------|-------------------|-------------|
| HA0004. | QIN14F003/QIN/ | 29/01/2014 | LAND | QIN14F003/QIN/ | 29/01/2014 | LAND |
| Initial poker gauge readings(01/2014)- Port: Top 64.35mm,Bottom 63.80mm; Stbd: Top 64.45mm,Bottom 63.55mm. | | | | | | |
| HA0005. | QIN14F003/QIN/ | 18/01/2014 | LAND | QIN14F003/QIN/ | 18/01/2014 | LAND |
| IMO no. permanently marked in accordance with SOLAS (consolidated edition 2004) Ch XI-1 Reg 3 | | | | | | |
| HA0007. | BOM15P122/BOM/ | 25/03/2015 | TPD | BOM15P122/BOM/ | 12/03/2015 | TPD |
| Following are used for cargo fuel tanks: | | | | | | |
| NO.1 C.F.O.TK (P),Fr.40-51 | | | | | | |
| NO.1 C.F.O.TK (S),Fr.40-51 | | | | | | |
| NO.2 C.F.O.D.B TK (P),Fr.30-40 | | | | | | |
| NO.2 C.F.O.D.B TK (S),Fr.30-40 | | | | | | |
| NO.3 C.F.O.TK (P),Fr.16-30 | | | | | | |
| NO.3 C.F.O.TK (S),Fr.16-30 | | | | | | |
| Following are used for bunker fuel tanks: | | | | | | |
| NO.3 F.O D.B TK (C),Fr.16-30 | | | | | | |
| F.O.DAY TK(P),Fr.40-47 | | | | | | |
| F.O.DAY TK(S),Fr.40-47 | | | | | | |
| HA0008. | BOM15P122/BOM/ | 25/03/2015 | TPD | BOM15P122/BOM/ | 12/03/2015 | TPD |
| Oil Residues waste to be retained on board and to be discharged to reception facility. | | | | | | |
| MA0002. | | | SMA | IT ADDLNOTE19012016A | 19/01/2016 | SMA |
| Upon completion of the first tail shaft survey scheduled on or after 1 Jan 2016, new tailshaft survey notation as per Class Rule requirement (Rule change notice No.2 - Jan 2016) is to be recommended for assignment. | | | | | | |
| An additional information is to be recommended providing date of withdrawal of the tail shaft, type of survey performed, type of propeller connection, tailshaft survey method (as per changes to rule requirement) which may be applied at the next tailshaft survey with due date. | | | | | | |
| MA0003. | | | SMA | IT ADDLNOTE11052016 | 11/05/2016 | SMA |
| High frequency(HF) radio-communications equipment capable of operating narrow-band direct printing(NBDP), if fitted, to be updated to meet the new channeling arrangements contained in the 2012 Radio Regulations HF, Appendix 17, Part B, Section II & III (HF Direct-printing telegraphy) by the first safety radio survey after 1 January 2024. | | | | | | |
| HA0006. | BOM15P122/BOM/ | 13/03/2015 | BBH | BOM16P181/BOM/ | 30/03/2016 | |
| International AFS certificate now issued which replaces statement of compliance issued earlier to the vessel.TBT free anti-fouling system to be repled as per AFS Convention and Endorsement of records issued at the next dry docking for continued validity of the AFS certificate. | | | | | | |
| HA0011. | BOM16P181/BOM/ | 06/04/2016 | BBH | BOM16P181/BOM/ | 30/03/2016 | |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Vessel to be provided with immersion suit , suitably pressure tested as per MSC/cir 1114 before undertaking any voyage outside BIMMS area as per DGS circular 14NT(5).

HA0012. QIN14F003/QIN/ 29/01/2014 LAND QIN14F003/QIN/ 29/01/2014 LAND

Vessel is exempted from below requirements as required of COLREG 72 with condition that a search light should be fitted to warn other approaching vessels as necessary, details refer the letter no. 41-NT(16)/2004-pt-I issued by GOI dtd 17/12/2013.

- a) Rule 23-a-(ii): Second mast head light.
- b) Annex 1-2-(f) (ii): Vertical spacing between all round light and mast head light. However it should not be less than 1 meter.

HA0013. RArora Info/H.O./IR 11/03/2014 RArora Info/H.O./IR 11/03/2014

DGS vide letter ref: SS/RSC/2250 dated 29/01/2014, exempted the coaming height requirement for flush hatches on freeboard deck under the provisions of Part II/Para 9 of first schedule, M.S. (Loadline) Rules 1979/Rg 14-1of International convention of Loadlines 1966 as modified by 1988 protocol, subject to condition that : (i) Hatches be kept closed at sea and suitable marking on both sides of hatch cover to that effect being displayed at the hatch location (ii) Weather-tightness is maintained at all times.

HA0014. SUNI BOM17P018/BOM/ 25/01/2017

Revised format of the Supplement to the IOPP certificate, adopted through IMO Res. MEPC. 265(68) is now issued to the vessel vide report no BOM17P018

HA0015. SUNI BOM17P018/BOM/ 25/01/2017

Arrangement in respect of oil residues (sludge) tank(s) on the vessel is verified for compliance with Paragraph 3.3 of the revised MARPOL Annex I/ Reg.12 adopted through MEPC. 266(68) vide report no BOM17P018

HA0016. SUNI BOM17P018/BOM/ 25/01/2017 SUNI

Revised format of the Cargo Ship Safety Construction Certificate adopted through IMO Res. MSC. 395(95) is now issued to the vessel vide report no BOM17P018

MA0104. BOM17P018/BOM/ 27/01/2017 SUNI BOM17P018/BOM/ 25/01/2017

As per owner's request ,Vessel's area of operation downgraded to Coast of India from A1+A2+A3.

MA0105. BOM17P018/BOM/ 27/01/2017 SUNI BOM17P018/BOM/ 25/01/2017

Vessel's operating in Indian Coast exempted from the requirement of Shore Based Maintenance Contract (SBMC) as per DGS Order No. 04 of 2012 dtd 30/05/2012.

MA0106. BOM17P018/BOM/ 27/01/2017 SUNI BOM17P018/BOM/ 25/01/2017

Additional VHF-DSC and SAT-C provided onboard.

MA0107. BOM17P215/BOM/ 11/04/2017 BKUM BOM17P215/BOM/ 10/04/2017 BKUM

Port Tail shaft (oil gland) : Stern tube seals and chrome liner(aft and fwd) are replaced by OEM approved spares .

MA0109. SMA IT ADDLNOTE08092017 08/09/2017 SMA

Revised format of the supplement to IOPP certificate(Form B) adopted through IMO resolution MEPC 276(70) is to be issued at first renewal survey on or after 1 March 2018.

MA0110. SMA IT ADDLNOTE30112017 01/12/2017 SMA

As per Government of India, Engineering circular number 06 of 2017, the Company is required to carry out cyber-risk assessment and incorporate the mitigation procedures in the safety management system manual after due review by RO prior to 1st January 2021.

HA0118. BOM17P469/BOM/ 25/07/2017 SUNI BOM17P469/BOM/ 24/07/2017

As per owner's request certificate of survey issued for wrong serial no and power of both main engines in certificate of registry.Corrected certificate of Registry to be placed onboard and to be verified by attending surveyor.

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

HA0119. SMA IT ADDLNOTE27042018 27/04/2018 SMA

A-60 Class Fire Doors manufactured by COSMO Co. Ltd., certified to MED or Type Approved and produced between November 2013 and July 2017, have been reported with partly missing insulation material. Existence of such fire doors is to be verified and reported at the next survey. Surveyor is to confirm affected door if any has been repaired as per manufacturer's procedure with evidence of repair work having accepted & endorsed by COSMO Co. Ltd., or has been replaced with doors meeting the 2010 FTP Code. Where repair to affected door has not been undertaken, H.O.(STS) is to be contacted for necessary guidance.

MA0111. PDP IT ADDLNOTE11102018 11/10/2018 PDP

When products as assigned for carriage on a type 2 ship in the IBC Code are intended to be carried, vessel is to comply with the provisions of the OSV Chemical Code (except for the amended stability provisions in chapter 2 of the OSV Chemical Code), at the next Annual / Intermediate / Renewal - Safety Construction Survey falling due after 1 September 2018.

MA0112. PGM IT ADDLNOTE16012019 16/01/2019 PGM

Fuel consumption data for the ship in accordance with DGS Engineering Circular No. 02 of 2018 - (Name of the Ship, IMO No. / Official No., Type of Ship, GT/ Deadweight, NT, Total Fuel Consumption (All types of Fuel), Rated Power of Main and Auxiliary Engine in KW, Whether the ship is supplied with Shore Electric Power during port stay) is to be submitted to IRS by 30th April 2020 for the calendar year 2019 and thereafter by 30th April of each calendar year for the previous calendar year.



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Compliance to New Regulations:

| Code | Description | Date Verified / Complied With | Report Reference |
|--------|---|----------------------------------|------------------|
| Z0001. | As required by SOLAS Ch.II-2 Reg.15.2.2.6, an onboard means of recharging breathing apparatus cylinders used during drills is to be provided or a suitable number of spare cylinders to be carried on board to replace those used during drills by 1 July 2014 which will be verified by surveyor at first survey after 1 July 2014. | 12/03/2015 | BOM15P122/BOM/ |
| Z0002. | As required by SOLAS Ch.II-2 Reg.10.10.1, self-contained compressed air breathing apparatus of fire-fighter's outfits to comply with paragraph 2.1.2.2 of chapter 3 of the Fire Safety Systems Code (i.e. Compressed air breathing apparatus to be fitted with an audible alarm and a visual or other device which will alert the user before the volume of the air in the cylinder has been reduced to no less than 200 l) by 1 July 2019. | | |
| Z0003. | A minimum of two two-way portable radiotelephone apparatus for each fire party for fire fighter's communication to be carried on board (as required by SOLAS Ch.II-2 Reg.10.10.4) not later than the first survey after 1 July 2018. Those two-way portable radiotelephone apparatus to be of an explosion proof type or intrinsically safe. | | |
| Z0004. | Ship-specific plans and procedures for recovery of persons from the water to be placed on board (as required by SOLAS Ch.III Reg.17-1) by the first periodical or renewal safety equipment survey of the ship to be carried out after 1 July 2014 whichever comes first. | 12/03/2015 | BOM15P122/BOM/ |
| Z0005. | During the first Intermediate/ Renewal survey of MARPOL Annex VI (whichever occurs first) on or after 1 January 2013, SEEMP be verified on board and the vessel be issued with International Energy Efficiency Certificate. | 12/03/2015 | BOM15P122/BOM/ |
| Z0006. | Appropriate portable atmosphere testing instrument/s (as a minimum capable of measuring concentrations of oxygen, flammable gases or vapours, hydrogen sulphide and carbon monoxide) will be required (SOLAS Ch.XI-1 Reg.7) to be carried on board from 01/07/2016. Instruments carried under other requirements may satisfy this regulation. Suitable means shall be provided for the calibration of all such instrument/s. | 06/07/2016 | BOM16P410/BOM/ |

Continuous Survey List(s)



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

List of Surveyable Items

List Of Machinery Items...

| Code | Status | Postpone Date | Cycle | Date | Next Due Date | Description | |
|------|--------|------------------|-------|---------|------------------|---|----|
| 0017 | | | 5 | | | Centre Port Inline Trunk Piston Type Engine | 42 |
| 0024 | | | 5 | 01/2014 | 01/2019 | NO.1 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0031 | | | 5 | 01/2014 | 01/2019 | NO.2 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0048 | | | 5 | 01/2014 | 01/2019 | NO.3 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0055 | | | 5 | 01/2014 | 01/2019 | NO.4 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0062 | | | 5 | 01/2014 | 01/2019 | NO.5 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0079 | | | 5 | 01/2014 | 01/2019 | NO.6 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0086 | | | 5 | 01/2014 | 01/2019 | NO.7 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0093 | | | 5 | 01/2014 | 01/2019 | NO.8 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0103 | | | 5 | 01/2014 | 01/2019 | NO.1 Main Journal & Bearing | |
| 0110 | | | 5 | 01/2014 | 01/2019 | NO.2 Main Journal & Bearing | |
| 0127 | | | 5 | 01/2014 | 01/2019 | NO.3 Main Journal & Bearing | |
| 0134 | | | 5 | 01/2014 | 01/2019 | NO.4 Main Journal & Bearing | |
| 0141 | | | 5 | 01/2014 | 01/2019 | NO.5 Main Journal & Bearing | |
| 0158 | | | 5 | 01/2014 | 01/2019 | NO.6 Main Journal & Bearing | |
| 0165 | | | 5 | 01/2014 | 01/2019 | NO.7 Main Journal & Bearing | |
| 0172 | | | 5 | 01/2014 | 01/2019 | NO.8 Main Journal & Bearing | |
| 0189 | | | 5 | 01/2014 | 01/2019 | NO.9 Main Journal & Bearing | |
| 0196 | | | 5 | 01/2014 | 01/2019 | NO.1 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0206 | | | 5 | 01/2014 | 01/2019 | NO.2 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0213 | | | 5 | 01/2014 | 01/2019 | NO.3 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0220 | | | 5 | 01/2014 | 01/2019 | NO.4 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0237 | | | 5 | 01/2014 | 01/2019 | NO.5 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0244 | | | 5 | 01/2014 | 01/2019 | NO.6 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0251 | | | 5 | 01/2014 | 01/2019 | NO.7 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0268 | | | 5 | 01/2014 | 01/2019 | NO.8 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0275 | | | 5 | 01/2014 | 01/2019 | Engine Trial | |
| 0282 | | | 5 | 01/2014 | 01/2019 | Insulation Exhaust Manifold & Piping | |
| 0299 | | | 5 | 01/2014 | 01/2019 | Crankcase Doors & Relief Devices | |
| 0309 | | | 5 | 01/2014 | 01/2019 | Crankshaft Alignment | |
| 0316 | | | 5 | 01/2014 | 01/2019 | Oil Mist Detector | |
| 0323 | | | 5 | 01/2014 | 01/2019 | Camshaft/S & Camshaft/S Drive | |
| 0330 | | | 5 | 01/2014 | 01/2019 | Bed Plates, Frames, Tie Rods, Holding Down Bolts & Chocks | |
| 0347 | | | 5 | 01/2014 | 01/2019 | Starting & Reversing Gear | |
| 0354 | | | 5 | 01/2014 | 01/2019 | Super Charger | |
| 0361 | | | 5 | 01/2014 | 01/2019 | Main Engine Air Cooler | |
| 0378 | | | 5 | 01/2014 | 01/2019 | Main Engine Attached Sea Water Cooling Pump | |
| 0385 | | | 5 | 01/2014 | 01/2019 | Main Engine Attached Fresh Water Cooling Pump | |
| 0392 | | | 5 | 01/2014 | 01/2019 | Main Engine Attached Lub.Oil Circulating Pump | |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone Date | Cycle | Date | Next Due Date | Description | |
|------|--------|------------------|-------|---------|------------------|---|----|
| 0402 | | | 5 | 01/2014 | 01/2019 | Main Engine Attached O.F Booster Pump | |
| 0419 | | | 5 | 01/2014 | 01/2019 | Coupling | |
| 0426 | | | 5 | 01/2014 | 01/2019 | Thrust | |
| 0433 | | | 5 | | | Centre Stbd Inline Trunk Piston Type Engine | 84 |
| 0440 | | | 5 | 01/2014 | 01/2019 | NO.1 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0457 | | | 5 | 01/2014 | 01/2019 | NO.2 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0464 | | | 5 | 01/2014 | 01/2019 | NO.3 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0471 | | | 5 | 01/2014 | 01/2019 | NO.4 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0488 | | | 5 | 01/2014 | 01/2019 | NO.5 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0495 | | | 5 | 01/2014 | 01/2019 | NO.6 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0505 | | | 5 | 01/2014 | 01/2019 | NO.7 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0512 | | | 5 | 01/2014 | 01/2019 | NO.8 Cyl, Cvr, Pstn, Con Rod, C. Pin Brg & Webs, Vlvs & Gears | |
| 0529 | | | 5 | 01/2014 | 01/2019 | NO.1 Main Journal & Bearing | |
| 0536 | | | 5 | 01/2014 | 01/2019 | NO.2 Main Journal & Bearing | |
| 0543 | | | 5 | 01/2014 | 01/2019 | NO.3 Main Journal & Bearing | |
| 0550 | | | 5 | 01/2014 | 01/2019 | NO.4 Main Journal & Bearing | |
| 0567 | | | 5 | 01/2014 | 01/2019 | NO.5 Main Journal & Bearing | |
| 0574 | | | 5 | 01/2014 | 01/2019 | NO.6 Main Journal & Bearing | |
| 0581 | | | 5 | 01/2014 | 01/2019 | NO.7 Main Journal & Bearing | |
| 0598 | | | 5 | 01/2014 | 01/2019 | NO.8 Main Journal & Bearing | |
| 0608 | | | 5 | 01/2014 | 01/2019 | NO.9 Main Journal & Bearing | |
| 0615 | | | 5 | 01/2014 | 01/2019 | NO.1 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0622 | | | 5 | 01/2014 | 01/2019 | NO.2 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0639 | | | 5 | 01/2014 | 01/2019 | NO.3 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0646 | | | 5 | 01/2014 | 01/2019 | NO.4 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0653 | | | 5 | 01/2014 | 01/2019 | NO.5 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0660 | | | 5 | 01/2014 | 01/2019 | NO.6 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0677 | | | 5 | 01/2014 | 01/2019 | NO.7 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0684 | | | 5 | 01/2014 | 01/2019 | NO.8 O.F. Inj. Pump, H.P O.F Pipes & Shielding | |
| 0691 | | | 5 | 01/2014 | 01/2019 | Engine Trial | |
| 0701 | | | 5 | 01/2014 | 01/2019 | Insulation Exhaust Manifold & Piping | |
| 0718 | | | 5 | 01/2014 | 01/2019 | Crankcase Doors & Relief Devices | |
| 0725 | | | 5 | 01/2014 | 01/2019 | Crankshaft Alignment | |
| 0732 | | | 5 | 01/2014 | 01/2019 | Oil Mist Detector | |
| 0749 | | | 5 | 01/2014 | 01/2019 | Camshaft/S & Camshaft/S Drive | |
| 0756 | | | 5 | 01/2014 | 01/2019 | Bed Plates, Frames, Tie Rods, Holding Down Bolts & Chocks | |
| 0763 | | | 5 | 01/2014 | 01/2019 | Starting & Reversing Gear | |
| 0770 | | | 5 | 01/2014 | 01/2019 | Super Charger | |
| 0787 | | | 5 | 01/2014 | 01/2019 | Main Engine Air Cooler | |
| 0794 | | | 5 | 01/2014 | 01/2019 | Main Engine Attached Sea Water Cooling Pump | |
| 0804 | | | 5 | 01/2014 | 01/2019 | Main Engine Attached Fresh Water Cooling Pump | |
| 0811 | | | 5 | 01/2014 | 01/2019 | Main Engine Attached Lub.Oil Circulating Pump | |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone Date | Cycle | Date | Next Due Date | Description | |
|------|--------|------------------|-------|---------|------------------|--|-----|
| 0828 | | | 5 | 01/2014 | 01/2019 | Main Engine Attached O.F Booster Pump | |
| 0835 | | | 5 | 01/2014 | 01/2019 | Coupling | |
| 0842 | | | 5 | 01/2014 | 01/2019 | Thrust | |
| 0859 | | | 5 | | | Port Main Reduction Gearing | 92 |
| 0866 | | | 5 | 01/2014 | 01/2019 | Pinion/S & Wheel/S | |
| 0873 | | | 5 | 01/2014 | 01/2019 | Shaft/S Coupling/S, Clutch(Es) & Bearing/S | |
| 0880 | | | 5 | 01/2014 | 01/2019 | Thrust | |
| 0897 | | | 5 | 01/2014 | 01/2019 | Coupling/Clutch For Shaft Generator | |
| 0907 | | | 5 | 01/2014 | 01/2019 | Attached Lub.Oil Pump | |
| 0914 | | | 5 | 01/2014 | 01/2019 | Elastic Coupling | |
| 0921 | | | 5 | 01/2014 | 01/2019 | Foundation Bolts & Chocks | |
| 0938 | | | 5 | | | Stbd Main Reduction Gearing | 100 |
| 0945 | | | 5 | 01/2014 | 01/2019 | Pinion/S & Wheel/S | |
| 0952 | | | 5 | 01/2014 | 01/2019 | Shaft/S Coupling/S, Clutch(Es) & Bearing/S | |
| 0969 | | | 5 | 01/2014 | 01/2019 | Thrust | |
| 0976 | | | 5 | 01/2014 | 01/2019 | Coupling/Clutch For Shaft Generator | |
| 0983 | | | 5 | 01/2014 | 01/2019 | Attached Lub.Oil Pump | |
| 0990 | | | 5 | 01/2014 | 01/2019 | Elastic Coupling | |
| 1001 | | | 5 | 01/2014 | 01/2019 | Foundation Bolts & Chocks | |
| 1018 | | | 5 | | | Port Shafting Arrangement | 103 |
| 1025 | | | 5 | 01/2014 | 01/2019 | Intermediate Shaft & Bearing/S | |
| 1032 | | | 5 | 01/2014 | 01/2019 | Clutch For Main Engine Shafting | |
| 1049 | | | 5 | | | Stbd Shafting Arrangement | 106 |
| 1056 | | | 5 | 01/2014 | 01/2019 | Intermediate Shaft & Bearing/S | |
| 1063 | | | 5 | 01/2014 | 01/2019 | Clutch For Main Engine Shafting | |
| 1070 | | | 5 | | | Auxiliary Machinery | 116 |
| 1087 | | | 5 | 01/2014 | 01/2019 | Port Generator Aux.Engine With Attachments & Coolers | |
| 1094 | | | 5 | 01/2014 | 01/2019 | Centre Generator Aux.Engine With Attachments & Coolers | |
| 1104 | | | 5 | 01/2014 | 01/2019 | Stbd Generator Aux.Engine With Attachments & Coolers | |
| 1111 | | | 5 | 01/2014 | 01/2019 | Emerg.Gen.Engine With Attachments & Coolers | |
| 1128 | | | 5 | 01/2014 | 01/2019 | Port Steering Gear Machinery Unit | |
| 1135 | | | 5 | 01/2014 | 01/2019 | Stbd Steering Gear Machinery Unit | |
| 1142 | | | 5 | 01/2014 | 01/2019 | Port Windlass Machinery Unit | |
| 1159 | | | 5 | 01/2014 | 01/2019 | Stbd Windlass Machinery Unit | |
| 1166 | | | 5 | 01/2014 | 01/2019 | First Start Arrangement Trial | |
| 1173 | | | 5 | | | Compressed Air System | 123 |
| 1180 | | | 5 | 01/2014 | 01/2019 | Port Starting Air Comp. Incl. Cooler & Safety Devices | |
| 1197 | | | 5 | 01/2014 | 01/2019 | Stbd Starting Air Comp. Incl. Cooler & Safety Devices | |
| 1207 | | | 5 | 01/2014 | 01/2019 | Port Starting Air Receiver & Safety Devices | |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone Date | Cycle | Date | Next Due Date | Description | |
|------|--------|------------------|-------|---------|------------------|---|-----|
| 1214 | | | 5 | 01/2014 | 01/2019 | Stbd Starting Air Receiver & Safety Devices | |
| 1221 | | | 5 | 01/2014 | 01/2019 | Aux. Air Receiver & Safety Devices | |
| 1238 | | | 5 | 01/2014 | 01/2019 | Starting Air Pipes & Valves | |
| 1245 | | | 5 | | | Fuel System | 128 |
| 1252 | | | 5 | 01/2014 | 01/2019 | Upper O.F Transfer Pump | |
| 1269 | | | 5 | 01/2014 | 01/2019 | Lower O.F Transfer Pump | |
| 1276 | | | 5 | 01/2014 | 01/2019 | Dirty Oil Pump | |
| 1283 | | | 5 | 01/2014 | 01/2019 | O.F Pipes/Valves/Filters | |
| 1290 | | | 5 | | | Lub.Oil System | 138 |
| 1300 | | | 5 | 01/2014 | 01/2019 | Port Main Engine Lub.Oil Pump | |
| 1317 | | | 5 | 01/2014 | 01/2019 | Stbd Main Engine Lub.Oil Pump | |
| 1324 | | | 5 | 01/2014 | 01/2019 | Port Main Engine Standby/Priming Pump | |
| 1331 | | | 5 | 01/2014 | 01/2019 | Stbd Main Engine Standby/Priming Pump | |
| 1348 | | | 5 | 01/2014 | 01/2019 | Main Engine Lub.Oil Cooler | |
| 1355 | | | 5 | 01/2014 | 01/2019 | Port Lub.Oil Cooler | |
| 1362 | | | 5 | 01/2014 | 01/2019 | Stbd Lub.Oil Cooler | |
| 1379 | | | 5 | 01/2014 | 01/2019 | Purifier Electric Heater | |
| 1386 | | | 5 | 01/2014 | 01/2019 | Lub.Oil Pipes/Valves/Filters | |
| 1393 | | | 5 | | | Cooling System | 147 |
| 1403 | | | 5 | 01/2014 | 01/2019 | Deck Machinery Sea Water Cooling Pump | |
| 1410 | | | 5 | 01/2014 | 01/2019 | Sea Water Pipes/Valves/Filters | |
| 1427 | | | 5 | 01/2014 | 01/2019 | No.1 B/T S.W Cooling Pump | |
| 1434 | | | 5 | 01/2014 | 01/2019 | No.2 B/T S.W Cooling Pump | |
| 1441 | | | 5 | 01/2014 | 01/2019 | Stern Thruster Sea Water Cooling Pump | |
| 1458 | | | 5 | 01/2014 | 01/2019 | Port Main Engine Fresh Water Cooler | |
| 1465 | | | 5 | 01/2014 | 01/2019 | Stbd Main Engine Fresh Water Cooler | |
| 1472 | | | 5 | 01/2014 | 01/2019 | Fresh Water Pipes/Valves/Filters | |
| 1489 | | | 5 | | | Hydraulic System | 161 |
| 1496 | | | 5 | 01/2014 | 01/2019 | Port Hydraulic Pump/Servo Unit For Control Pitch Propeller | |
| 1506 | | | 5 | 01/2014 | 01/2019 | Stbd Hydraulic Pump/Servo Unit For Control Pitch Propeller | |
| 1513 | | | 5 | 01/2014 | 01/2019 | Circ. Pump For Pitch Propeller System | |
| 1520 | | | 5 | 01/2014 | 01/2019 | Pipes/Valves/Filters For Pitch Propeller System | |
| 1537 | | | 5 | 01/2014 | 01/2019 | Pipes/Valves/Filters For Remote Operation | |
| 1544 | | | 5 | 01/2014 | 01/2019 | Port Hyd. Pump For A.H.T Winch | |
| 1551 | | | 5 | 01/2014 | 01/2019 | Centre Hyd. Pump For A.H.T Winch | |
| 1568 | | | 5 | 01/2014 | 01/2019 | Stbd Hyd. Pump For A.H.T Winch | |
| 1575 | | | 5 | 01/2014 | 01/2019 | Cooler For Bow Thruster System | |
| 1582 | | | 5 | 01/2014 | 01/2019 | Pipes/Valves/Filters For Bow Thruster | |
| 1599 | | | 5 | 01/2014 | 01/2019 | Hyd. Pump, Relief Devices & System For Thruster Unit | |
| 1609 | | | 5 | 01/2014 | 01/2019 | Port Hyd. Pump & Relief Devices For Hyd. Windlass Mahcy. Unit | |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone Date | Cycle | Date | Next Due Date | Description | |
|------|--------|------------------|-------|---------|------------------|---|-----|
| 1616 | | | 5 | 01/2014 | 01/2019 | Stbd Hyd. Pump & Relief Devices For Hyd. Windlass Mahcy. Unit | |
| 1623 | | | 5 | | | Bilge & Ballast System | 172 |
| 1630 | | | 5 | 01/2014 | 01/2019 | Centifugal Bilge Pump | |
| 1647 | | | 5 | 01/2014 | 01/2019 | No.1 Bilge Pump | |
| 1654 | | | 5 | 01/2014 | 01/2019 | No.2 Bilge Pump | |
| 1661 | | | 5 | 01/2014 | 01/2019 | Port Bilge/Ballast/Fire/G.S.Pump | |
| 1678 | | | 5 | 01/2014 | 01/2019 | Stbd Bilge/Ballast/Fire/G.S.Pump | |
| 1685 | | | 5 | 01/2014 | 01/2019 | Dirty Bilge Pump | |
| 1692 | | | 5 | 01/2014 | 01/2019 | Emergency Fire Pump & Prime Mover | |
| 1702 | | | 5 | 01/2014 | 01/2019 | Working Test Of Bilge System Incl. Emerg. Suction | |
| 1719 | | | 5 | 01/2014 | 01/2019 | Bilge Pipes/Valves/Filters | |
| 1726 | | | 5 | 01/2014 | 01/2019 | Ballast Pipes/Valves/Filters | |
| 1733 | | | 5 | | | Electrical System | 186 |
| 1740 | | | 5 | 01/2014 | 01/2019 | Port Gen. & Governor Running Test | |
| 1757 | | | 5 | 01/2014 | 01/2019 | Centre Gen. & Governor Running Test | |
| 1764 | | | 5 | 01/2014 | 01/2019 | Stbd Gen. & Governor Running Test | |
| 1771 | | | 5 | 01/2014 | 01/2019 | Port Shaft Gen. & Governor Running Test | |
| 1788 | | | 5 | 01/2014 | 01/2019 | Stbd Shaft Gen. & Governor Running Test | |
| 1795 | | | 5 | 01/2014 | 01/2019 | Switch Boards & Fittings | |
| 1805 | | | 5 | 01/2014 | 01/2019 | Emerg. Source Of Power & Associated Equipment | |
| 1812 | | | 5 | 01/2014 | 01/2019 | Navigation Lights, Indicators | |
| 1829 | | | 5 | 01/2014 | 01/2019 | Cables/Expansion Boxes/Fittings Etc. | |
| 1836 | | | 5 | 01/2014 | 01/2019 | Circuit Breakers | |
| 1843 | | | 5 | 01/2014 | 01/2019 | Motor/S, Control/S & Starter/S | |
| 1850 | | | 5 | 01/2014 | 01/2019 | Transformer/S | |
| 1867 | | | 5 | 01/2014 | 01/2019 | Megger Test | |
| 1874 | | | 5 | | | Instrumentation & Automation Equipment | 190 |
| 1881 | | | 5 | 01/2014 | 01/2019 | Control System For Main Engine | |
| 1898 | | | 5 | 01/2014 | 01/2019 | Control System For Bow Thruster | |
| 1908 | | | 5 | 01/2014 | 01/2019 | Control System For Control Pitch Propeller | |
| 1915 | | | 5 | | | Sea Connections | 201 |
| 1922 | | | 5 | 01/2014 | 01/2019 | Port Side Suctions | |
| 1939 | | | 5 | 01/2014 | 01/2019 | Port Side Discharges | |
| 1946 | | | 5 | 01/2014 | 01/2019 | Stbd Side Suctions | |
| 1953 | | | 5 | 01/2014 | 01/2019 | Stbd Side Discharges | |
| 1960 | | | 5 | 01/2014 | 01/2019 | No.1 Bow Thruster Propeller | |
| 1977 | | | 5 | 01/2014 | 01/2019 | No. 1 Bow Thruster Driving Machy. Unit | |
| 1984 | | | 5 | 01/2014 | 01/2019 | No.2 Bow Thruster Propeller | |
| 1991 | | | 5 | 01/2014 | 01/2019 | No.2 Bow Thruster Driving Machy. Unit | |
| 2002 | | | 5 | 01/2014 | 01/2019 | Aft Thruster Propeller | |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone Date | Cycle | Date | Next Due Date | Description |
|------|--------|------------------|-------|---------|------------------|----------------------------------|
| 2019 | | | 5 | 01/2014 | 01/2019 | Aft Thruster Driving Machy. Unit |

List Of Hull Items...

| Code | Status | Postpone Date | Cycle | Date | Description |
|------|--------|------------------|-------|---------|--|
| 5012 | | | 5 | 01/2014 | Thickness Determination |
| 5029 | | | 5 | 01/2014 | Superstructures |
| 5036 | | | 5 | 01/2014 | Forecastle |
| 5043 | | | 5 | 01/2014 | Deck House/S |
| 5050 | | | 5 | 01/2014 | Upr Deck Plating |
| 5067 | | | 5 | 01/2014 | Forecastle Deck Plating |
| 5074 | | | 5 | 01/2014 | Forepeak Space/S |
| 5081 | | | 5 | 01/2014 | Accommodation Space/S |
| 5098 | | | 5 | 01/2014 | Store Space/S |
| 5108 | | | 5 | 01/2014 | Cement Room |
| 5115 | | | 5 | 01/2014 | Fwd Bow Thruster Compartment |
| 5122 | | | 5 | 01/2014 | Engine Room |
| 5139 | | | 5 | 01/2014 | Port Chain Locker |
| 5146 | | | 5 | 01/2014 | Stbd Chain Locker |
| 5153 | | | 5 | | Fore Peak W.B/D.W Tank (92-FE) |
| 5160 | | | 5 | 01/2014 | Examination |
| 5177 | | | 5 | 01/2014 | Test |
| 5184 | | | 5 | | No.6 Port W.B/D.W Tank (Ae-5) |
| 5191 | | | 5 | 01/2014 | Examination |
| 5201 | | | 5 | 01/2014 | Test |
| 5218 | | | 5 | | No.6 Stbd W.B/D.W Tank (Ae-5) |
| 5225 | | | 5 | 01/2014 | Examination |
| 5232 | | | 5 | 01/2014 | Test |
| 5249 | | | 5 | | No.2 Port W.B/D.W Tank(49-73) |
| 5256 | | | 5 | 01/2014 | Examination |
| 5263 | | | 5 | 01/2014 | Test |
| 5270 | | | 5 | | No.2 Stbd W.B/D.W Tank(49-73) |
| 5287 | | | 5 | 01/2014 | Examination |
| 5294 | | | 5 | 01/2014 | Test |
| 5304 | | | 5 | | No.2 Centre W.B/D.W Tank(60-73) |
| 5311 | | | 5 | 01/2014 | Examination |
| 5328 | | | 5 | 01/2014 | Test |
| 5335 | | | 5 | | No.3 Port W.B/D.W Tank(30-40) |
| 5342 | | | 5 | 01/2014 | Examination |
| 5359 | | | 5 | 01/2014 | Test |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone Date | Cycle | Date | Description |
|------|--------|------------------|-------|---------|--|
| 5366 | | | 5 | | No.3 Stbd W.B/D.W Tank(30-40) |
| 5373 | | | 5 | 01/2014 | Examination |
| 5380 | | | 5 | 01/2014 | Test |
| 5397 | | | 5 | | No.4 Port W.B/D.W Tank(16-30) |
| 5407 | | | 5 | 01/2014 | Examination |
| 5414 | | | 5 | 01/2014 | Test |
| 5421 | | | 5 | | No.4 Stbd W.B/D.W Tank(16-30) |
| 5438 | | | 5 | 01/2014 | Examination |
| 5445 | | | 5 | 01/2014 | Test |
| 5452 | | | 5 | | No.5 Port W.B/D.W Tank(5-16) |
| 5469 | | | 5 | 01/2014 | Examination |
| 5476 | | | 5 | 01/2014 | Test |
| 5483 | | | 5 | | No.5 Centre W.B/D.W Tank(5-16) |
| 5490 | | | 5 | 01/2014 | Examination |
| 5500 | | | 5 | 01/2014 | Test |
| 5517 | | | 5 | | No.5 Stbd W.B/D.W Tank(5-16) |
| 5524 | | | 5 | 01/2014 | Examination |
| 5531 | | | 5 | 01/2014 | Test |
| 5548 | | | 5 | | No.1 Port Mun. Tank/Brine Tank/R.O.(Fr.30-40) |
| 5555 | | | 5 | 01/2014 | Examination |
| 5562 | | | 5 | 01/2014 | Test |
| 5579 | | | 5 | | No.1 Stbd Mun. Tank/Brine Tank/R.O.(Fr.30-40) |
| 5586 | | | 5 | 01/2014 | Examination |
| 5593 | | | 5 | 01/2014 | Test |
| 5603 | | | 5 | | No.2 Mun. Tank/Brine Tank/R.O.(Abv)(Fr.23-30) |
| 5610 | | | 5 | 01/2014 | Examination |
| 5627 | | | 5 | 01/2014 | Test |
| 5634 | | | 5 | | No.3 Mun. Tank/Brine Tank/R.O.(Abv)(Fr.16-24) |
| 5641 | | | 5 | 01/2014 | Examination |
| 5658 | | | 5 | 01/2014 | Test |
| 5665 | | | 5 | | No.2 Mun. Tank/Brine Tank/R.O.(Abv)(Fr.9-16) |
| 5672 | | | 5 | 01/2014 | Examination |
| 5689 | | | 5 | 01/2014 | Test |
| 5696 | | | 5 | | No.1 Port Potable Water Tank(83-92) |
| 5706 | | | 5 | 01/2014 | Examination |
| 5713 | | | 5 | 01/2014 | Test |
| 5720 | | | 5 | | No.1 Stbd Potable Water Tank(83-92) |
| 5737 | | | 5 | 01/2014 | Examination |
| 5744 | | | 5 | 01/2014 | Test |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone Date | Cycle | Date | Description |
|------|--------|------------------|-------|---------|---|
| 5751 | | | 5 | | No.2 Port Potable Water Tank(73-83) |
| 5768 | | | 5 | 01/2014 | Examination |
| 5775 | | | 5 | 01/2014 | Test |
| 5782 | | | 5 | | No.2 Stbd Potable Water Tank(73-83) |
| 5799 | | | 5 | 01/2014 | Examination |
| 5809 | | | 5 | 01/2014 | Test |
| 5816 | | | 5 | | No.3 Port Potable Water D.B. Tank(73-83) |
| 5823 | | | 5 | 01/2014 | Examination |
| 5830 | | | 5 | 01/2014 | Test |
| 5847 | | | 5 | | No.3 Stbd Potable Water D.B. Tank(73-83) |
| 5854 | | | 5 | 01/2014 | Examination |
| 5861 | | | 5 | 01/2014 | Test |
| 5878 | | | 5 | | No.4 Port Potable Water Tank(54-71) |
| 5885 | | | 5 | 01/2014 | Examination |
| 5892 | | | 5 | 01/2014 | Test |
| 5902 | | | 5 | | No.4 Stbd Potable Water Tank(54-71) |
| 5919 | | | 5 | 01/2014 | Examination |
| 5926 | | | 5 | 01/2014 | Test |
| 5933 | | | 5 | | No.1 Port D.O.Tank(40-51) |
| 5940 | | | 5 | 01/2014 | Examination |
| 5957 | | | 5 | 01/2014 | Test |
| 5964 | | | 5 | | No.1 Stbd D.O.Tank(40-51) |
| 5971 | | | 5 | 01/2014 | Examination |
| 5988 | | | 5 | 01/2014 | Test |
| 5995 | | | 5 | | No.2 Port D.O.Tank(30-40) |
| 6006 | | | 5 | 01/2014 | Examination |
| 6013 | | | 5 | 01/2014 | Test |
| 6020 | | | 5 | | No.2 Stbd D.O.Tank(30-40) |
| 6037 | | | 5 | 01/2014 | Examination |
| 6044 | | | 5 | 01/2014 | Test |
| 6051 | | | 5 | | No.3 Port D.O.Tank(16-30) |
| 6068 | | | 5 | 01/2014 | Examination |
| 6075 | | | 5 | 01/2014 | Test |
| 6082 | | | 5 | | No.3 Centre D.O.Tank(16-30) |
| 6099 | | | 5 | 01/2014 | Examination |
| 6109 | | | 5 | 01/2014 | Test |
| 6116 | | | 5 | | No.3 Stbd D.O.Tank(16-30) |
| 6123 | | | 5 | 01/2014 | Examination |
| 6130 | | | 5 | 01/2014 | Test |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone | | Date | Description |
|------|--------|----------|-------|---------|--------------------------------------|
| | | Date | Cycle | | |
| 6147 | | | 5 | | F.O.Daily Tank(40-47) |
| 6154 | | | 5 | 01/2014 | Examination |
| 6161 | | | 5 | 01/2014 | Test |
| 6178 | | | 5 | | No.1 Dry Bulk Tank(75-81+0.4) |
| 6185 | | | 5 | 01/2014 | Examination |
| 6192 | | | 5 | 01/2014 | Test |
| 6202 | | | 5 | | No.2 Dry Bulk Tank(75-81+0.4) |
| 6219 | | | 5 | 01/2014 | Examination |
| 6226 | | | 5 | 01/2014 | Test |
| 6233 | | | 5 | | No.3 Dry Bulk Tank(31+0.2-38) |
| 6240 | | | 5 | 01/2014 | Examination |
| 6257 | | | 5 | 01/2014 | Test |
| 6264 | | | 5 | | No.4 Dry Bulk Tank(31+0.2-38) |
| 6271 | | | 5 | 01/2014 | Examination |
| 6288 | | | 5 | 01/2014 | Test |
| 6295 | | | 5 | | Aux. L.O. Tank(49-53) |
| 6305 | | | 5 | 01/2014 | Examination |
| 6312 | | | 5 | 01/2014 | Test |
| 6329 | | | 5 | | Main L.O. Tank(49-53) |
| 6336 | | | 5 | 01/2014 | Examination |
| 6343 | | | 5 | 01/2014 | Test |
| 6350 | | | 5 | | Foam Tank(40-53) |
| 6367 | | | 5 | 01/2014 | Examination |
| 6374 | | | 5 | 01/2014 | Test |
| 6381 | | | 5 | | Dispersant Tank(40-53) |
| 6398 | | | 5 | 01/2014 | Examination |
| 6408 | | | 5 | 01/2014 | Test |
| 6415 | | | 5 | | Sewage Tank(66-72) |
| 6422 | | | 5 | 01/2014 | Examination |
| 6439 | | | 5 | 01/2014 | Test |
| 6446 | | | 5 | | F.O. Overflow Tank(51-55) |
| 6453 | | | 5 | 01/2014 | Examination |
| 6460 | | | 5 | 01/2014 | Test |
| 6477 | | | 5 | | Dirty Oil Tank(55-60) |
| 6484 | | | 5 | 01/2014 | Examination |
| 6491 | | | 5 | 01/2014 | Test |
| 6501 | | | 5 | | Bilge Holding Tank(55-60) |
| 6518 | | | 5 | 01/2014 | Examination |
| 6525 | | | 5 | 01/2014 | Test |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone Date | Cycle | Date | Description |
|------|--------|------------------|-------|---------|---|
| 6532 | | | 5 | | Hyd. Oil Tank(47-49) |
| 6549 | | | 5 | 01/2014 | Examination |
| 6556 | | | 5 | 01/2014 | Test |
| 6563 | | | 5 | | Port Shaft Tunnel |
| 6570 | | | 5 | 01/2014 | Examination |
| 6587 | | | 5 | 01/2014 | Test |
| 6594 | | | 5 | | Stbd Shaft Tunnel |
| 6604 | | | 5 | 01/2014 | Examination |
| 6611 | | | 5 | 01/2014 | Test |
| 6628 | | | 5 | 01/2014 | Under Engines |
| 6635 | | | 5 | 01/2014 | Echo Sounding Compartment |
| 6642 | | | 5 | 01/2014 | Steering Gear Compartment |
| 6659 | | | 5 | 01/2014 | Bow Thruster Compartment |
| 6666 | | | 5 | 01/2014 | Windlass |
| 6673 | | | 5 | 01/2014 | Anchors/S |
| 6680 | | | 5 | 01/2014 | Cables |
| 6697 | | | 5 | 01/2014 | Steering Gear |
| 6707 | | | 5 | 01/2014 | Hand Pump/S |
| 6714 | | | 5 | 01/2014 | Sounding Pipes |
| 6721 | | | 5 | 01/2014 | Air Pipe/S |
| 6738 | | | 5 | 01/2014 | Mast/S |
| 6745 | | | 5 | 01/2014 | Fire Equipment |
| 6752 | | | 5 | 01/2014 | Communication-Bridge To Engine Room |
| 6769 | | | 5 | 01/2014 | Communication-Bridge To Alternative Steering Position |
| 6776 | | | 5 | 01/2014 | Helm Indicator |
| 6783 | | | 5 | 01/2014 | Water Tight Door/S |
| 6790 | | | 5 | 01/2014 | Hatchways & Closing Appliances |
| 6800 | | | 5 | 01/2014 | Ventilators, Airpipes & Closing Appliances |
| 6817 | | | 5 | 01/2014 | Casing & Their Closing Appliances |
| 6824 | | | 5 | 01/2014 | Skylights & Closing Appliances |
| 6831 | | | 5 | 01/2014 | Deckhouses, Companionways & Closing Appliances |
| 6848 | | | 5 | 01/2014 | Superstructures & Closing Appliances |
| 6855 | | | 5 | 01/2014 | Windows, Side Scuttles, Deadlights & Closing Appliances |
| 6862 | | | 5 | 01/2014 | Scupper, Sanitary Discharge & Valves |
| 6879 | | | 5 | 01/2014 | Guard Rails & Bulwarks |
| 6886 | | | 5 | 01/2014 | Freeing Ports |
| 6893 | | | 5 | 01/2014 | Gangways, Walkways & Lifelines |
| 6903 | | | 5 | | Emergency Towing Arrangement |
| 6910 | | | 5 | 01/2014 | Examination |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

| Code | Status | Postpone | | Date | Description |
|------|--------|----------|-------|---------|-------------|
| | | Date | Cycle | | |
| 6927 | | | 5 | 01/2014 | Test |

List Of Other Items...

| Code | Status | Postpone | | Date | Description |
|------|--------|----------|-------|---------|-------------------------------------|
| | | Date | Cycle | | |
| 4011 | | | 5 | | Port Tailshaft Survey |
| 4028 | | | 5 | 01/2014 | Crack Detection Of Screw Shaft Cone |
| 4035 | | | 5 | 01/2014 | Approved Oil Gland |
| 4042 | | | 5 | 01/2014 | Propeller |
| 4059 | | | 5 | 01/2014 | Tailshaft |
| 4066 | | | 5 | 01/2014 | Sternbush |
| 4073 | | | 5 | | Stbd Tailshaft Survey |
| 4080 | | | 5 | 01/2014 | Crack Detection Of Screw Shaft Cone |
| 4097 | | | 5 | 01/2014 | Approved Oil Gland |
| 4107 | | | 5 | 01/2014 | Propeller |
| 4114 | | | 5 | 01/2014 | Tailshaft |
| 4121 | | | 5 | 01/2014 | Sternbush |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Survey History - 5 Year Cycle

| Survey Station | Report Number | Survey Held | First Visit Date | Last Visit Date |
|----------------|---------------|---|------------------|-----------------|
| MUMBAI | BOM18P060 | AS,AS(AGNI),AS(DP),COFLHNSAS,IAPPAS,ILLAS,IOPAS,SAFAS,SEQAS,SPSAS,SRTPS | 29/01/2018 | 13/03/2018 |
| MUMBAI | BOM17P469 | OCS | 24/07/2017 | 24/07/2017 |
| MUMBAI | BOM17P356 | MARPOL Annex IV GENEX | 02/06/2017 | 02/06/2017 |
| MUMBAI | BOM17P215 | AS(DP),CHNGFE3,DAMM,GENEXICC | 03/04/2017 | 10/04/2017 |
| MUMBAI | BOM17P018 | AS,AS(AGNI),CHNGFE3,COFLHNSAS,DS,IAPPAS,ILLAS,IOPAS,IS,SAFAS,SPSAS,SRTPS | 12/01/2017 | 01/04/2017 |
| MUMBAI | BOM16P591 | COC(H) | 14/09/2016 | 14/09/2016 |
| MUMBAI | BOM16P410 | COC(H) | 06/07/2016 | 06/07/2016 |
| MUMBAI | BOM16P181 | AS,AS(AGNI),AS(DP),CMPAFSGENEX,COFLHNSAS,DAMH,IAPPAS,ILLAS,IOPAS,MARPOL Annex IV GENEX,SAFAS,SEQAS,SPSAS,SRTPS | 28/03/2016 | 30/03/2016 |
| MUMBAI | BOM15P122 | AS,AS(AGNI),AS(DP),CMPAFSGENEX,COFLHNSAS,IAPPAS,IEE CIN,ILLAS,IMDGGENEX,IOPAS,MARPOL Annex IV GENEX,SAFAS,SEQAS,SPSAS,SRTPS | 03/03/2015 | 12/03/2015 |

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Information related to e-Certificate

Class & Statutory certificates issued are indicated in the survey status as "HC" for certificates issued in hardcopy format & "DC" for Digitally signed Certificate (e-Certificate).

IRS will be issuing hard copy as well as e-certificates for a period of 5 years from the commencement of this service.

Verification / downloading of e-Certificates

- e-Certificate, can be verified on the IRClass website at address <http://www.irclass.org/marine/e-certificates-verification> by using a Tracking ID which appears at the bottom of each page of an e-Certificate.
- e-Certificate verification from IRClass website can also be done by scanning the QR Code, printed on the bottom right side of the certificate using any QR CODE scanning application available in app store.
- e-Certificate can be downloaded from IRClass website by using the Unique Tracking ID provided to each certificate or by scanning the QR code printed on the face of the certificate. e-certificates can also be directly downloaded from IRClass website by using login credentials provided to the company.

Endorsement of e-certificates after completion of Periodical Surveys/Audits/Inspections:

- Endorsement by IRS surveyor

Upon completion of Periodical Surveys/Audits/Inspections attending surveyor/auditor shall update endorsement details in the e-Certificates online immediately but within two working days. As an interim measure a copy of the e-certificate shall be printed from IRClass website & endorsed towards surveys being completed and left on board. The hard copy of the certificate available on board the vessel also should be endorsed and within 2 days on receipt of the information that the digitally signed e-certificate is available on irclass website the owner after confirming so, may withdraw the manually endorsed e-certificate left on board by the surveyor.

- Endorsement by flag or other RO of the flag

When surveys are completed by flag administration or other RO surveyors, attending surveyor/auditor shall print the e-certificate from IRClass website & endorse towards surveys being completed. Copy of survey report along with endorsed certificate shall be forwarded electronically to ecertificates@irclass.org

Contact us

Request for issuance of e-certificates / related queries are to be sent to ecertificates@irclass.org

Phone : +91 22 30519538 / 656 / 781

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

Information for ship owners / managers

1. Any repairs to the hull, machinery and equipment either as a result of damage or wear and tear which are required for maintenance of class are to be carried out under inspection of and to the satisfaction of the surveyors.
2. Where a vessel is damaged to an extent resulting in towage outside port limits, it shall be the Owners' responsibility to notify IRS at the first practicable opportunity.
3. Any alteration proposed to be carried out to approved scantlings and arrangements of the hull machinery or equipment are to meet with approval of IRS. Such approved alterations are to be carried out under the inspection of, and to the satisfaction of surveyors.
4. When a ship is detained by Port State Control, IRS is to be immediately notified by the owner / operator for arranging attendance by a Surveyor.
5. When a vessel meets any accident such as fire, collision etc., it shall be the Owners' responsibility to notify IRS at the first practicable opportunity.
6. It shall be the Owners' responsibility to maintain the vessel in between surveys.
7. If the vessel's class has been laid up, in order to maintain the laid up status, it shall be the Owners' responsibility to offer the vessel for general examination within the window of periodical survey.
8. When a vessel is under survey, it shall be Owners' responsibility to notify IRS if vessel is sailing out of port limits.
9. The class of a vessel will be liable to be suspended if the Owner fails to notify IRS of any damage to the ship's hull, machinery or equipment, which may adversely affect classification of the vessel or subsequently fails to arrange for the survey as may be advised by IRS.
10. The class of a vessel will be automatically suspended from the expiry date of Certificate of Class or by the expiry date of any extension granted, if the special survey has not been completed by the due date and an extension has not been agreed to, or the vessel is not under attendance by the surveyor with a view to complete the surveys prior to resuming service.
11. The class of a vessel will also be automatically suspended if the annual, intermediate survey become overdue.
12. The class of a vessel will be subject to a suspension procedure if an item of continuous survey is overdue at the time of annual survey, unless the item is dealt with or postponed by agreement.
13. The class of the vessel will also be subject to a suspension procedure if recommendations and/or conditions of class are not dealt with by the due date or postponed by agreement, by the due date.
14. The class of a vessel will be liable to be suspended if alterations are carried out on items which may affect the classification of the ship without informing IRS, except in the case of emergency repairs.
15. The class of a ship is liable to be withheld or, if already granted, may be withdrawn in case of any non-payment of fees or expenses chargeable for the service rendered.
16. Where any ship proceeds to sea with less freeboard than that approved by IRS or when the freeboard marks are placed higher on the ship's sides than the position assigned or approved by IRS, the ship's class will be suspended.
17. When it is found that a ship is being operated in a manner contrary to that agreed at the time of classification, or is being operated in conditions or in areas more onerous than those agreed, the class will be suspended.

For any enquiries please contact : IRCLASS

Telephone: 022 - 30519400, 71199400

E-Mail: ho@irclass.org

Direct fax line: 022 25703611

www.irclass.org

Survey status generated on: 09/07/2019 07:13 AM



Survey Status Report

Name : TAG 13
Status : Class Suspended

IR Number : 43961
IMO Number : 9680827

DISCLAIMER :-

Information provided in ship survey status by IRClass is solely provided for the convenience of Owners or Managers as a guide to their ship's survey status and in no way substitute for advice from IRClass.

Neither Indian Register of Shipping, nor any of its employees, assures any responsibility for the accuracy or legal liability for any loss or damage that may be sustained as a result of using their services.



Ships and Technical Services Division

**52A, Adishankaracharya Marg,
Opp Powai Lake, Powai, Mumbai,
Maharashtra, India-400072.**

Tel.: 91 22 30519400, 71199400 (0) Fax: 91 22 25703611

Corporate website: www.irclass.org

Email: ho@irclass.org